

Master 2.34.1

Released 10.10.2023

New features

New supported devices

A90, A90BT, AS90

Fixed bugs

1. **2.X.X S96(V2)** Orange-black wire failed to operate in input mode on units with serial number ES96V2P...

Known bugs

1. **2.32.X GEN7 GEN7(V2) E96(V2) S96(V2)** Programming procedure to factory immobilizer bypass does not work on some Mazda vehicles (bypass via RX/TX).
 2. **2.34.1 E96(V2) S96(V2)** Immobilizer bypass stopped working after parking until restarted on vehicles with factory immobilizer bypass via LIN, RX/TX, IMO/IMI (GM, Honda, KIA etc).
 3. **2.34.1 E96(V2) S96(V2)** CAN sometimes stops working (both reading statuses and control functions) until the system is restarted on vehicles with a single wire bus.
 4. **2.34.1 E96(V2)** Key fob stopped working when ignition On in vehicles having single LIN wire (Hyundai, KIA, GM etc).
-