

# Master 2.34.4

Released 28.11.2023

## New features

No features

## Fixed bugs

1. **2.32.X GEN7, GEN7(V2), E96(V2), S96(V2)** Programming procedure to bypass factory immobilizer didn't work on some Mazda vehicles (bypass via RX/TX).
2. **2.34.1 E96(V2), S96(V2)** Immobilizer bypass stopped working after parking until restarted on vehicles with factory immobilizer bypass via LIN, RX/TX, IMO/IMI (GM, Honda, KIA etc).
3. **2.34.1 E96(V2), S96(V2)** Improved stability of CAN operation on single wire CAN bus vehicles (both reading statuses and control functions).
4. **2.34.1 E96(V2)** Key fob stopped working when ignition On in vehicles having single LIN wire (Hyundai, KIA, GM etc).

## Known bugs

No

---