

Master 2.38.5

Released 10.12.2024

New features

No

Fixed Bugs

2.X.X **A90 A90BT E96(V2) GEN7(V2)** Optimization of integrated RF-transceiver power control

Known bugs

2.X.X **GEN7(V2)** On most Chinese-built vehicles, reading statuses and control via CAN stops when engine is started until the main unit is rebooted.
