

# Master 2.33.3

Released 11.09.2023

## New features

Architecture optimization to support different device revisions

GEN7(V2) E96(V2) S96(V2) E90(V2)

## Fixed bugs

No

## Known bugs

1. 2.X.X S96(V2) Orange-black wire failed to operate in input mode on units with serial number ES96V2P..

***\*This firmware version is intended for security systems with serial numbers in the format GEN7 S..., E96V2 S..., E96V2P S..., ES96 S..., ES96P S..., excluding E96V2L S... and ES96L S***

Выпущена 11.09.2023

## Новые функции

Архитектурная оптимизация поддержки разных ревизий устройств

## Исправленные ошибки

Отсутствуют.

## Известные ошибки

1. 2.X.X S96(V2) На блоках с серийным номером ES96V2P... не работает оранжево-черный провод в режиме входа.

*\*Данная версия ПО предназначена для охранных комплексов с серийными номерами формата GEN7 S..., E96V2 S...,E96V2P S..., ES96 S...,ES96P S..., кроме E96V2L S..., ES96L S...*

---