

# Master 2.38.5

Released 10.12.2024

## New features

No

## Fixed Bugs

**2.X.X** **A90 A90BT E96(V2) GEN7(V2)** Optimization of integrated RF-transceiver power control

## Known bugs

**2.X.X** **GEN7(V2)** On most Chinese-built vehicles, reading statuses and control via CAN stops when engine is started until the main unit is rebooted.

---