

Master 2.43.3

Released 03.03.2026

New features

1. No

Fixed bugs

1. **2.X.X E96(V2) E96V2E90L S96(V2) GEN7(V2)** Factory immobiliser bypass wasn't working on Daihatsu vehicles.

Known bugs

1. No
-