





Table of possible indications

| Event | Tag (LED) | Sound indication | Notes |
|---|--|--------------------------------|---|
| Warning of upcoming engine blocking | — | intermittent sound signals | Take action to stop the car |
| Discharged tag battery | image not found or type unknown  | 3 sound signals | Install new battery |
| Normal security mode | image not found or type unknown  | — | If the LED flashes once at button pressing, the tag is outside the coverage range. Security functions are disabled in the service mode. |
| Antihijack mode | image not found or type unknown  | — | |
| Service mode | image not found or type unknown  | — | |
| Successful tag authorization | — | 1 sound signal | |
| Tag is absent. Prompt to enter the unlocking code | — | long sound signal | For immobilizers i95 ECO, i95. |
| Normal mode. Tag is absent | — | 1 sound signal every 2 minutes | If the tag was lost after motion start (in the normal security mode) |
| Failure of the hood lock circuit | — | 2 sound signals | Fix hood lock circuit |