





# Table of possible indications

Event	Tag (LED)	Sound indication	Notes
Warning of upcoming engine blocking	—	intermittent sound signals	Take action to stop the car
Discharged tag battery	image not found or type unknown 	3 sound signals	Install new battery
Normal security mode	image not found or type unknown 	—	If the LED flashes once at button pressing, the tag is outside the coverage range. Security functions are disabled in the service mode.
Antihijack mode	image not found or type unknown 	—	
Service mode	image not found or type unknown 	—	
Successful tag authorization	—	1 sound signal	
Tag is absent. Prompt to enter the unlocking code	—	long sound signal	For immobilizers i95 ECO, i95.
Normal mode. Tag is absent	—	1 sound signal every 2 minutes	If the tag was lost after motion start (in the normal security mode)
Failure of the hood lock circuit	—	2 sound signals	Fix hood lock circuit